CHANGE ORDER FORM

	Project Title:	Ar	nkeny Kirkendall Public Library						
city of	Contractor: Stahl Construction								
Ankeny	Address: 1250 SW District Dr.								
bringing it all tagether	Finance Budget Code:	928.2928.4	412 <i>Fina</i>	nce Project#	928.4412				
	Vendor Project or Invoice	#:	0	PO #	0				
	Original Contract Date:	-	2, 2018	Vendor#	7227				
Change Order Number:	6								
hange Order Date:	December 6, 2018								
urpose of Change Order:									
		1 11	1 1 1	A					
and the roof	aming members as deck.		J		7				
Details of Change Order:	DESCRIPTION:	LIBUTO CO	IANITITY CHANCE	UNIT PRICE	EXTENDED PRICE				
. —	DESCRIPTION	UNITS QU	ANTITY CHANGE 1.00	\$ 7,770.00	\$ 7,770.00				
1	RFI 48	+ ' +	1.00	\$ 7,770.00	\$ -				
3		-			\$ -				
4					\$ -				
5					\$				
6			Mark Turking		\$ -				
7	And the second second	V-12.14	Jv	- 11 - 11 - 11 - 11 - 11 - 11 - 11 - 1	\$ -				
8					\$ -				
9					\$ -				
10					\$ -				
hange Order Number:	makes the follow	ing adjustm	ents to the co	ontract:	\$ 7,770.00				
	Otabl Construction		Pagard of	Change Orders					
Contractor Accepted: Stahl Construction Firm Name			#	Date	Amount				
Chi Na	12.6	18		ontract Amount	\$12,767,000.00				
Signature	Date			gust 20, 2018	\$ 10,510.00				
			2 Sep	tember 7, 2018	\$ 7,453.00				
rchitect Approved:	OPN Architects			ctober 4, 2018	\$ 6,766.00				
Firm Na	nme			tober 29, 2018	\$ 4,817.20				
	2018	5 Janes	ry 7, 2019	† 8,468.00					
Signature	Date		6 James	ry 7,2019	\$ 7,770.00				
	City of Ankeny	10 - 1 6	7						
wner Accepted:	11 02128/18	8 9							
			10						
Signature	Title		11						
Signature		12							
	Date		13						
			14						
ttest for Owner:			15						
			Paul o	antract Amazout	12,812,784.2				
Signature	Title		Revised C	ontract Amount					
	Date		-						
	Date								

	1844 AND 1	e at th		CC	ONTR	ACTOR C.C). RI	EQUEST E	BRE	AKDOWN FOR	RM
ST	" AI	HL	Ø 3								
	Projec	ct Nan	ne:			Anken	y Kirk	endall Publi	c Lib	orary	
		roject	-				OF	N-16826000			
Referer			_					RFI 48			
Reques			_					RFI 48			
Keque	31 DC3	criptic			Ke La	MATERI	ΔΙ				
						Description			1	Add/Deduct	
Quantity		Jnits	\dashv			Boom Lift				1200	
1	-	ea	\dashv		We	elding Machine				360	
1	-	ea	\dashv			3x3x1/4 Cont				1250	
			\dashv								
				and the same	01						
						-				,	
		**									
			_								
						7				Total:	\$2,810.00
										Sales Tax:	\$0.00
									Se	ection Subtotal:	\$2,810.00
		W. D.				MANPOV	VEE			CONTRACTOR OF THE PARTY OF THE	
						ACRES TO SERVICE AND ACRES	A			Add/Deduct	
Position	F	lours		Rate		Subtotal		Per Diem			
Superintend		1	@	\$95.00	=	\$95.00	+	\$0.00	=	\$95.00 \$65.00	
Field engine		1	@	\$65.00	=	\$65.00	+		=	\$3,920.00	
Iron Worke	er	49	@	\$80.00	=	\$3,920.00	+		=	\$0.00	
	_		@		=	\$0.00 \$0.00	+		=	\$0.00	
			@	Harrie Data	=	\$0.00	-			ection Subtotal:	\$4,080.00
Note: Include	Labor	burde	n ın ı	Hourly Rate			NIT	DACTO			
				2ND	IIIE	R SUBCO	ו אול	RACIO	K	Add/Daduat	
Contracto	or Nan	ne			Descr	iption of Work			\vdash	Add/Deduct	
			_								
			-								
									s	ection Subtotal:	\$0.0
		STANK.	1677		C	ERTIFIC	ΔΤΙ	ON			
经验证证				YES EN WES							
	-								Re	quest Subtotal:	\$6,890.0
Signa	ture:									Overhead:	\$345.0
Signature:									Fee		\$345.0
										Ins. and bond	\$190.0
Name/	Title.			Г	avid D	ominguez				ins. and bond	Ψ100.0



Request for Information, #048

Ankeny Kirkendall Public Library 1250 SW District Dr Ankeny, IA 50023 Project # OPN-16826000

Stahl Construction Company

Date Created: 11/13/2018

To Author Company
OPN Architects Stahl Construction Company
200 Fifth Avenue SE 5755 Wayzata Blvd
Cedar Rapids, IA 52401 St. louis Park, MN 55416

CC Urgency

Subject Spec Section Drawing Category

Missing edge angle detail Architectural, Structural

Question Date Required: 11/15/2018

In details A5/A104 and J25/A353 it shows an angle running along the 7 line and the 9 line that the cold form framing is attached to. I am unable to find this angle detailed on the structural drawing. Please provide the structural detailing of this angle.

Response Date Answered:

Provide L3x3x1/4 Cont. at the top of the k joists.

SBI: AJG 2018-11-15

Answered By: